

ISSUE NO. : 10-013	DATE : July 28th. 2010	PAGES : 1 OF 1
--------------------	------------------------	----------------



SUBJECT	Notice of a SPARK PLUG CAP modification
MODEL	GT250(R)N, GV250N
EFFECTIVE F/M NO	Attached

This service bulletin is written to inform you of a SPARK PLUG CAP modification.

1. Details

- SILICON TUBE has been applied to SPARK PLUG CAP.

2. PART

	Before	After
Picture		
Part No.	33510-05C01	33500H88400

3. Application

Model	VIN No.	ENGINE No.	Application date
GV250N	KM4MJ54AXB1501289	GV250-136934	16/06/10
	KM4MJ54A5A1101042	GV250-136856	16/06/10
GT250RN	KM4MJ55B5A1101288	GT250-136786	14/06/10
	KM4MJ5277A1700287	GT250-137298	23/06/10
GT250N	KM4MJ55A0A1500679	GT250-137191	23/06/10
	KM4MJ5276A1300141	GT250-137205	24/06/10

- The End -